Parish Lengthsman Report

April 2021

Works Complete

Regular walkabouts

Public toilets maintenance and inspections

Underpass checks and clearing

Mowing the grass of – the roundabout, visibility areas at the end of Taunton Road and Minehead Road, under the Broadgauge business park sign, Millers Way, Hamber Lea, outside of the toilets

Strimming of areas requiring it —East Combe, visibility at Stairfoot, visibility on the junction of B3224, visibility on junction of West Street to A358, area around posts and rails by Middlebrook Farm

Cut hedge at the end of Hither Mead where it meets Taunton Road

Cleared leaves on the road at Millers Way

Problems to report

Falling stones from a wall on Cothelstone Road on the right as you go up the hill by the sharp corner sign



Damaged finger bollards on the Cothelstone Road



Bollard broke off by the Co op



Jack Councill